Electrical Safety & LOTO Review Extended Operations Council Meeting R. C. McNair October 22, 2002



Assessment Team

Al	B	O E	rrج	ner
/ 11		V	<i>-</i>	

Joe Curtis

Emil Zitvogel

Tom Nehring

Steve Waski

NSLS

ESH&Q

NSLS

C-AD

PE

Jon Sandberg C-AD

John DiNicola PE

Joe Jahelka T&Q

John Usher IO

Bob McNair IO



Assessment Plan Development & Deployment

- Input from Laboratory Electrical Safety Committee
- Input from DOE
- ESH 1.5.0 Electrical Safety
- ESH 1.5.1 LOTO
- Lessons Learned/ORPS
- Facility Procedures
- Lab & Facility Training
- Notified Facilities 3-5 Weeks in Advance
- Worked Around Facility Schedule
- Provided Immediate Feedback to Line Management
- Assessment still in progress



Strengths

Configuration Management



Strengths

LOTO Token Boxes



Strengths

Auxiliary Lockbox



Strengths

Reusable Hold Tags



Strengths

- Checklist for LOTO during shift change
- Verification of released LOTO



Strengths

Use of Green "Disconnected Cable" tag



Strengths

Cable labelling database



Strengths

 New electric panels are clearly labeled



Strengths

 Newer facilities have updated drawings and accurate load list



Strengths

Line crew use of appropriate PPE



Strengths

Replacing Plexiglas with fire retardant material



Strengths

Communications of Lessons Learned



Areas For Improvement

 Approval of facility procedures by Laboratory Electrical Safety
 Officer

Areas For Improvement

Performance of annual reviews



Areas For Improvement

Logbook entries



Areas For Improvement

Locks applied without tags



Areas For Improvement

Tags applied without locks



Areas For Improvement

Legibility of tags



Areas For Improvement

Hold tag stubs



Areas For Improvement

Transfer of tags when personnel leave



Areas For Improvement

Key control in auxiliary facilities

Areas for Improvement

Logging of Caution tags



Areas for Improvement

Heeding Caution tag information



Areas for Improvement

Labeling of disconnected cables



Areas for Improvement

 Trenches left open with energized cables



Areas for Improvement

Load list in breaker panels/ MCC



Areas for Improvement

Spare breakers found energized



Areas for Improvement

Electrical drawings



Areas for Improvement

 Appropriate Personal Protective Equipment

Areas for Improvement

Hotsticks



Areas for Improvement

Unauthorized Electrical Work



Areas for Improvement

Housekeeping



ELECTRICAL SAFETY & LOTO REVIEW

Recommendations

- Supervisors shall conduct and document annual reviews as per ESH 1.5.1
- ESH Standard 1.5.0 needs to catch up with the Electrical Safety training.
































Brookhaven Science Associates U.S. Department of Energy







Brookhaven Science Associates U.S. Department of Energy









Brookhaven Science Associates U.S. Department of Energy





Brookhaven Science Associates U.S. Department of Energy
















Brookhaven Science Associates U.S. Department of Energy












Brookhaven Science Associates U.S. Department of Energy










Brookhaven Science Associates U.S. Department of Energy





Brookhaven Science Associates U.S. Department of Energy









Brookhaven Science Associates U.S. Department of Energy





Brookhaven Science Associates U.S. Department of Energy









ELECTRICAL SAFETY & LOTO REVIEW

Facilities Assessed

AGS

BGRR

NSLS

901

HFBR

Field work

